Sl.No	Package ID	Camp	Block	Lat	Long	Will the project potentially involve an influx of workers to the project location, and will the influx be considered significant for the local community?
						Under the sub-project of Deep Tara Tube Well (DTTW) at DRP Camp 3 the
1			AA-05	21.21214	92.14708	
						management. Noted that, the incoming workers will be very low in numbers, so there will be no competition to use those resources.
2			AA-05	21.208743	92.14843	Same as above.
3	•		AA-14	21.210379	92.14708	Same as above.
4			AA-20	21.212403	92.14803	Same as above.
5			AA-20	21.212328	92.14779	Same as above.
6			AA-20	21.212202	92.14804	Same as above.
7			AA-15	21.210993	92.14845	Same as above.
8			AA-15	21.210782	92.14861	Same as above.
9			AA-26	21.210053	92.14616	Same as above.
10			AA-03	21.208813	92.14938	Same as above.
11			AA-06	21.208807	92.14945	Same as above.
12			AA-06	21.208793	92.14982	Same as above.
13			AA-04	21.208948	92.14981	Same as above.
14	7B	3	AA-04	21.209157	92.14981	Same as above.
15	,		AA-04	21.209117	92.14943	Same as above.
16			DD ½ 01	21.210132	92.14731	Same as above.
17			DD ½ 02	21.209783	92.14693	Same as above.
18			DD ½ 06	21.208927	92.1482	Same as above.
19			DD ½ 03	21.208488	92.14932	Same as above.
20			DD ½ 05	21.20929	92.14897	Same as above.

21 AA-01 21.20861 92.14877 Same as above. 22 DD ½ 05 21.209058 92.14774 Same as above. 23 AA-01 21.208628 92.14898 Same as above. 24 DD-36 21.206828 92.15296 Same as above. 25 DD-34 21.206825 92.15244 Same as above. 26 DD-03 21.20692 92.15204 Same as above. 27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 30 AA-27 21.210345 92.14679 Same as above. 31 AA-29 21.21125 92.1479 Same as above. 32 AA-31 21.213653 92.14744 Same as above. 33 AA-31 21.213282 92.14719 Same as above. 34 AA-31 21.213289 92.1474 Same as above. 35 AA-24 21.213313 92.14823 Same as above.					
23 AA-01 21.208362 92.14898 Same as above. 24 DD-36 21.206628 92.15296 Same as above. 25 DD-34 21.206825 92.15244 Same as above. 26 DD-03 21.208442 92.15204 Same as above. 27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14709 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.213282 92.14774 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 39 AA-15 21.213913 92.14936 Same as abov	21	AA-01	21.20861	92.14877	Same as above.
24 DD-36 21.206628 92.15296 Same as above. 25 DD-34 21.206825 92.15244 Same as above. 26 DD-03 21.208442 92.15204 Same as above. 27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.2132182 92.14774 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 39 AA-15 21.213113 92.14984 Same as above. <td>22</td> <td>DD ½ 05</td> <td>21.209058</td> <td>92.14774</td> <td>Same as above.</td>	22	DD ½ 05	21.209058	92.14774	Same as above.
25 DD-34 21.206825 92.15244 Same as above. 26 DD-03 21.208442 92.15204 Same as above. 27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.213182 92.14774 Same as above. 36 AA-24 21.213218 92.14823 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 38 AA-15 21.213113 92.14994 Same as above. 40 AA-25 21.213657 92.14994 Same as above.	23	AA-01	21.208362	92.14898	Same as above.
26 DD-03 21.208442 92.15204 Same as above. 27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.213182 92.14774 Same as above. 36 AA-24 21.213218 92.14823 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14936 Same as above. 40 AA-25 21.213525 92.14928 Same as above.	24	DD-36	21.206628	92.15296	Same as above.
27 DD-35 21.20692 92.1535 Same as above. 28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.213182 92.14774 Same as above. 36 AA-24 21.213218 92.14823 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14938 Same as above. 41 AA-26 21.212529 92.14938 Same as above. 43 AA-22 21.21259 92.14981 Same as above	25	DD-34	21.206825	92.15244	Same as above.
28 AA-27 21.210413 92.14647 Same as above. 29 AA-27 21.210345 92.14658 Same as above. 30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 33 AA-31 21.213282 92.14719 Same as above. 34 AA-31 21.213182 92.14774 Same as above. 35 AA-24 21.213182 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.213313 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14934 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14945 Same as above. 42 AA-22 21.212598 92.14945 Same as ab	26	DD-03	21.208442	92.15204	Same as above.
AA-27 21.210345 92.14658 Same as above. AA-29 21.21125 92.14709 Same as above. AA-29 21.211408 92.14744 Same as above. AA-31 21.213653 92.14807 Same as above. AA-31 21.213282 92.14719 Same as above. AA-31 21.213182 92.14774 Same as above. AA-31 21.213182 92.14774 Same as above. AA-32 21.213218 92.14823 Same as above. AA-24 21.213218 92.14823 Same as above. AA-24 21.213218 92.14843 Same as above. AA-24 21.213218 92.14843 Same as above. AA-24 21.212947 92.14856 Same as above. AA-15 21.213113 92.14936 Same as above. AA-15 21.213945 92.14894 Same as above. AA-25 21.213525 92.14928 Same as above. AA-26 21.212529 92.14928 Same as above. AA-27 21.212529 92.14945 Same as above. AA-29 21.212529 92.14945 Same as above. AA-20 21.21265 92.14981 Same as above. AA-02 21.212894 92.14981 Same as above. AA-02 21.212894 92.14981 Same as above. DD ½ 07 21.208072 92.14943 Same as above. DD ½ 12 21.207178 92.14731 Same as above.	27	DD-35	21.20692	92.1535	Same as above.
30 AA-29 21.21125 92.14709 Same as above. 31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 33 AA-31 21.213282 92.14719 Same as above. 34 AA-31 21.213182 92.14774 Same as above. 35 AA-24 21.213218 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.21252 92.14945 Same as above. 43 AA-22 21.212598 92.14981 Same as above. 44 AA-20 21.212659 92.14981 Same as abo	28	AA-27	21.210413	92.14647	Same as above.
31 AA-29 21.211408 92.14744 Same as above. 32 AA-31 21.213653 92.14807 Same as above. 33 AA-31 21.213282 92.14719 Same as above. 34 AA-31 21.213182 92.14774 Same as above. 35 AA-24 21.213218 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.21947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14948 Same as above. 42 AA-22 21.212529 92.14981 Same as above. 43 AA-22 21.212659 92.14981 Same as above. 44 AA-20 21.212894 92.14981 Same as above. 45 AA-02 21.212894 92.14943 Same as ab	29	AA-27	21.210345	92.14658	Same as above.
32 AA-31 21.213653 92.14807 Same as above. 34 AA-31 21.213282 92.14719 Same as above. 35 AA-31 21.213182 92.14774 Same as above. 36 AA-24 21.213218 92.14823 Same as above. 37 AA-24 21.213313 92.14843 Same as above. 38 AA-15 21.213113 92.14856 Same as above. 39 AA-15 21.213113 92.14936 Same as above. 40 AA-25 21.213945 92.14894 Same as above. 41 AA-25 21.213525 92.14928 Same as above. 42 AA-25 21.212529 92.14938 Same as above. 43 AA-22 21.212598 92.14945 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same a	30	AA-29	21.21125	92.14709	Same as above.
33 AA-31 21.213282 92.14719 Same as above. 34 AA-31 21.213182 92.14774 Same as above. 35 AA-24 21.213218 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212529 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same a	31	AA-29	21.211408	92.14744	Same as above.
34 AA-31 21.213182 92.14774 Same as above. 35 AA-24 21.213218 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.21252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	32	AA-31	21.213653	92.14807	Same as above.
35 AA-24 21.213218 92.14823 Same as above. 36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	33	AA-31	21.213282	92.14719	Same as above.
36 AA-24 21.213313 92.14843 Same as above. 37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.21252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	34	AA-31	21.213182	92.14774	Same as above.
37 AA-24 21.212947 92.14856 Same as above. 38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. DD ½ 12 21.207178 92.14731 Same as above.	35	AA-24	21.213218	92.14823	Same as above.
38 AA-15 21.213113 92.14936 Same as above. 39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. DD ½ 07 21.208072 92.14943 Same as above. DD ½ 12 21.207178 92.14731 Same as above.	36	AA-24	21.213313	92.14843	Same as above.
39 AA-15 21.213945 92.14894 Same as above. 40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	37	AA-24	21.212947	92.14856	Same as above.
40 AA-25 21.213525 92.14928 Same as above. 41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. DD ½ 12 21.207178 92.14731 Same as above.	38	AA-15	21.213113	92.14936	Same as above.
41 AA-25 21.213657 92.14938 Same as above. 42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	39	AA-15	21.213945	92.14894	Same as above.
42 AA-22 21.212252 92.14945 Same as above. 43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	40	AA-25	21.213525	92.14928	Same as above.
43 AA-22 21.212598 92.14982 Same as above. 44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	41	AA-25	21.213657	92.14938	Same as above.
44 AA-20 21.21265 92.14981 Same as above. 45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	42	AA-22	21.212252	92.14945	Same as above.
45 AA-02 21.212894 92.14981 Same as above. 46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	43	AA-22	21.212598	92.14982	Same as above.
46 DD ½ 07 21.208072 92.14943 Same as above. 47 DD ½ 12 21.207178 92.14731 Same as above.	44	AA-20	21.21265	92.14981	Same as above.
47 DD ½ 12 21.207178 92.14731 Same as above.	45	AA-02	21.212894	92.14981	Same as above.
	46	DD ½ 07	21.208072	92.14943	Same as above.
48 DD ½ 11 21.20749 92.14693 Same as above.	47	DD ½ 12	21.207178	92.14731	Same as above.
	48	DD ½ 11	21.20749	92.14693	Same as above.

Package_WD_07B S

Is the project located	Section C1, General Labor Influx Screening	Section C2, Land
in a rural or remote		acquisition and
area?		stakeholder
		screening
project Of DTTW costruction and O&M located in a remote hilly and corrugated. The frequency and extent of contact, communicate between the local community and outsiders are limited and controlled by the respective CIC. After sattlement of DRP, the area isn't sensitive at environmental conditions. In this scheme area, no elephant migration routes exists (ref. IUCN). TheOXFAM is the WASH camp focal, UNHCR is acting area focal agency at Camp 3. About 75-100 DRP people will directly benefited from the sub-project (DTTW)	Regarding General Labor Influx screening process under the subproject (DTTW) establishment in the proposed areas, it has been reveled that no scope to arise labor influx situation. Total skilled Labor: 1-2, unskilled labor 3-5 need per DTTW installation. All of the unskilled labor will be engaged from the DRP community. No any foreign labor will be engaged. To establish the scheme tasks, some outsider labor, technicians will be engaged over there; so scope to arise social conflict may be raised. A complete Gender action plan already developed and approved, a full time Gender Specialist of this project has been assigned to oversee the GBV based issues for this subproject. The gender and gender-based violence issues (i.e. human trafficking, eve teasing, etc.) are being addressed through mainstreaming activities. As the mitigation measure the Social Safeguard team and GRC has been following the respective GRM, will aware on GBV and motivate the community through consultation meeting, counseling. Given the sensitivities in the camps areas (social, cultural, religious, gender, disabilities, orphan. No DRP shelters will be affected. However, during construction if any shelters require to shift, mitigation measures will be taken according to RPF. Consultations will be conducted with stakeholders, camp and block focal persons, and site management. During construction, if any shelters are affected, contractors are responsible to mitigate the impacts following the RPF as well.	
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
	Same as above.	Same as above.
Same as above.		
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.

Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above.
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above
Same as above.	Same as above.	Same as above

COVID-19 issue fot the sub-project intervention

Labor and Contractors management during COVID-19: For the sub-projects involving construction/civil works, contractors will develop specific procedures or plans so that adequate precautions are in place to prevent or minimize an outbreak of COVID-19, and what should be done if a worker gets sick:

- · Assessing the characteristics of the workforce, including those with underlying health issues or who may be otherwise at risk
- Confirming workers are fit for work, to include temperature testing and refusing entry to sick workers
- · Considering ways to minimize entry/exit to site or the workplace, and limiting contact between workers and the community/general public
- Training workers on hygiene and other preventative measures, and implementing a communication strategy for regular updates on COVID-19 related issues and the status of affected workers
- Treatment of workers who are or should be self-isolating and/or are displaying symptoms
- Assessing risks to continuity of supplies of medicine, water, fuel, food and PPE, taking into account international, national and local supply chains
- · Reduction, storage and disposal of medical waste
- · Adjustments to work practices, to reduce the number of workers and increase social distancing
- Expanding health facilities on-site compared to usual levels, developing relationships with local health care facilities and organize for the treatment of sick workers
- Building worker accommodations further apart, or having one worker accommodation in a more isolated area, which may be easily converted to quarantine and treatment facilities, if needed
- Establishing a procedure to follow if a worker becomes sick (following WHO guidelines)
- Implementing a communication strategy with the community, community leaders and local government in relation to COVID-19 issues on the site.

For supporting health facilities, plans or procedures will be in place to address the following issues:

- Obtaining adequate supplies of medical PPE, including gowns, aprons, curtains; medical masks and respirators (N95 or FFP2); gloves (medical, and heavy duty for cleaners); eye protection (goggles or face screens); hand washing soap and sanitizer; and effective cleaning equipment. Where relevant PPE cannot be obtained, the plan should consider viable alternatives, such as cloth masks, alcohol-based cleansers, hot water for cleaning and extra handwashing facilities, until such time as the supplies are available
- Training medical staff on the latest WHO advice and recommendations on the specifics of COVID-19
- Conducting enhanced cleaning arrangements, including thorough cleaning (using adequate disinfectant) of catering
 facilities/canteens/food/drink facilities, latrines/toilets/showers, common areas, including door handles, floors and all surfaces that are touched
 regularly.
 Training and providing cleaning staff with adequate PPE when cleaning consultation rooms and facilities used to treat infected
 patients

Implementing a communication sti	rategy/plan to support regular communication, accessible updates and clear messaging to health workers,
	Same as above.

Same as above.	
Same as above.	

Section C3, Social Capital Format Aiming to seek necessary support to accompish DTTW schemes in the E&S Screening Process we have listed down the concerned social institutes/bodies working in the camp area, intended project influence areas to enlist them for the possible inclusion in the management, and monitoring of the sub-projects. List the name of social institutes/ bodies under the given categorization along with the following information. Use separate sheet for each category of social institute/body. The information can be collected through secondary sources such as UNO Office or different development organizations that are involved with the community crisis projects, i.e.; Bangladesh Government agencies -Mr. Mahbubul Alam Talukder, RRRC Commissioner, CXB, Email rrccox@yahoo.com Engr. Ritthick Chowdhury, DPHE, Executive Engineer, CXB, Email. chowritthick@gmail.com Md. Mahfuzar Rahman, Camp-in-Charge, Camp-03 (Deputy Secretary) Camp3@rrrc.gov.bd Emmett Kearney, Area Focal Agency, UNHCR KearneyE@unhcr.org 01708 367828 Forhadul Hasan, Focal person, Oxfam, fhasan@oxfam.org 01677404554 Same as above. Same as above.

Same as above.
Same as above.
Same as above.
Same as above.
Same as above.
Same as above.
Same as above.
Same as above.
Same as above.
Same as above.

Photos

Same as above.
Same as above.